

## **Puget Sound Clean Air Agency**

110 Union Street, Suite 500 Seattle, WA 98101-2038 phone 206-343-8800/1-800-552-3565 fax 206-343-7522 www.pscleanair.org

## **Compliance Status Report**

Case No	me sh Grove Cement Co. cation (Address)	Evaluation Da	ate: 1/21/03   Ime	:
Name Ash Gro	ve Cement Co.	Responsible F Graig Gotro	Person, Title , Plant Manager	
	Address) Marginal Way So.	City Seattle, WA	Zip 98134	County King
Mailing Ad As Abov		City, State Seattle, WA	Zip 98134	Phone (206) 623-5596
dio: Age 22 <sup>n</sup> to 7 ng/	oserved no violations of our Agency's xin source test on the main exhaust sency reviewed of your dioxin source to through October 24th 2002. We observed on the content of the corrected to 7% oxygen limit for grees F.	stack and the coal est results for the served that Ash G eratures greater t	mill stack. On test that was o rove met the 0. han 400 degree	January 21 <sup>st</sup> 2003 th conducted on October .20 ng/dscm corrected es F and the 0.40
☐ _1 co	ould not make a compliance determina	ation because:		
	eed to consult with others. I will share	e my conclusions	with you either	in person, over the
☐ Ine	ed more information. Please submit	the following info	rmation by	:
ssued by:	Mario A Nuller for Elizabeth Gilpin, Inspector, 206-689-4026	Descritime	23/3	
Received by				
	signature		print na	me

Signing this document is not an admission of guilt



#### Working Together For Clean Air

www.pscleanair.org

February 3, 2003

Ph 206.343.8800

1.800.552.3565

Fax 206.343.7522

110 Union Street

Suite 500

Seattle, WA 98101-2038

Ash Grove Cement Company

c/o Craig Gotro

3801 E Marginal Way South

enforcement action in this case.

Seattle WA 98134

Re:

Ash Grove Cement Company (R11339)

Disposition of Written Warning Nos. 2-006631 and 2-006632

Based on the submittal of your passing Dioxin Source Test for the reporting

period of October 22 through October 24, 2002, this Agency considers the above-referenced matter closed as of this date and will take no further

EXECUTIVE DIRECTOR

Dennis J. McLerran

Dear Mr. Gotro:

BOARD OF DIRECTORS

CHAIR

Bill Evans

Tacoma City Councilman

KING COUNTY

Ron Sims, Executive

Gregory J. Nickels, Mayor

KITSAP COUNTY

Jan Angel, Commissioner

BREMERTON

Cary Bozeman, Mayor

PIERCE COUNTY

John Ladenburg, Executive

TACOMA

Bill Baarsma, Mayor

SNOHOMISH COUNTY

Jeff Sax, Councilman

EVERETT

Edward D. Hansen, Mayor

MEMBER AT LARGE

Janet Chalupnik

Thank you for your action to ensure compliance with Agency regulations and for joining with this Agency in efforts to achieve cleaner air.

Sincerely,

Elizabeth Gilpin

Inspector

EMG/mll

Mario Miller, Supervising Inspector

Mario A. Muller for

Fred Austin, Engineer

Melissa McAfee, Inspector



110 Union Street, Suite 500 Seattle, WA 98101-2038 Ph: 206.343.8800 / 1.800.552.3565 Fax: 206.343.7522 www.pscleanair.org

## **Puget Sound Clean Air Agency**

## **Compliance Status Report**

Inspection Date:	September	3 703
Timos (a taxa		

Time: <u>/2100 ph</u>

Case/Registration No.  Responsible Person, Title  Reg. 11339  Ash Grove Cement Co.  Craig Puljan Mgr.  Site Address  City  Zip  County  Mailing Address  City, State  City, State  Scattle, WA.  Phone  (206) 623-5596			
Reg. 11339	Ash Grove Cement	: Co.	Craig Puljan Mgr.
Site Address	City	Zip	County
3801 E. Margina	1 Way So Scattle	98134	King
Mailing Address	City, State	Zip	Phone
As Above	Scattle, W	/A. 98134	(206) 623-5596
Ç.4			

I observed no violations of our agency's regulations during my inspection in the areas I inspected.
🗖 🚶 could not make a compliance determination because:
I need to consult with others. I will share my conclusions with you either in person, over the phone, or in writing by
I need more information. Please submit the following information by within to days
1) During our compliance inspection of your facility on 9/3/03, we
Observed visible emissions from the kiln Cowling and the feed
End of the kiln during phase I of start up (prior to the
introduction of feet) We were unable to position ourselves
Issued By: Received By: CAS

Date/Time: 4/3/03 2:45 ph

## **Puget Sound Clean Air Agency**

Source Name: Ash Grove Conert Co Case No.:/Registration No.: 11339 CSR 9/3/03
Method 9 A readings.
Please collect method 9A readings for at least 20 minutes in any one hour from the kiln cowling and feed end of the Kiln during your next phase I kiln start up to determine co-appliance with Regulation I 9.03 (a).
Descriptions you used in obtaining these Values.
Issued By: Maheh M. Received By: CAS  Date/Time: 9/3/03 2:45 pm. Violation No.: C5R dated 9/3/03

### ASH GROVE CEMENT COMPANY



September 8, 2003

Ms. Elizabeth Gilpin Puget Sound Air Pollution Control Agency 110 Union Street, Suite 500 Seattle, WA. 98101-2038

Re: Compliance Status Report – September 3, 2003 Compliance Inspection

Dear Ms. Gilpin:

The above Compliance Status Report requested additional information:

#### **MERCURY**

The 2003 annual Hg concentrations, presented below, are based on results of recent raw mix and coal sampling for Hg at the Seattle plant. Since the results were <0.01 ppm for raw mix, ½ the detection limit was used (0.005 ppm). The Hg concentration data for tires was based on a recent in-house study of mercury concentrations in tires at one of our other facilities. The concentration for tires was calculated as an average from 25 data sets. The annual estimate adds a degree of conservatism by assuming 0% Hg partitions to the clinker.

Mercury	ppm		2002 tons used				2002 Hg input (lbs)
Raw feed	0.005	х	982876	1	1000000*2000	=	9.8
Coal	0.19	х	85677	7	1000000*2000	=	32.6
Tires	0.13	х	5499	/	1000000*2000	=	1.4
		П			Annual		43.8

#### **ARSENIC**

Based on results of a stack test conducted by Valid Results on August 6, 1996, the emission estimate for Arsenic has been calculated as 2.32x10<sup>-6</sup> lbs. As per ton of clinker produced. This translates to 1.61 lbs. As emitted in 2002.

Arsenic Emission factor	Clinker Produced	Emission
2.32x10 <sup>-6</sup> lbs. As per ton of clinker	693,842 tons	1.61 lbs.

If Ash Grove can provide any further information, please contact me.

Tours dury

Gerald J. Brown

Manager Safety and Environment

cc: Craig Puljan, Plant Manager

### ASH GROVE CEMENT COMPANY

February 18, 2004

Ms. Elizabeth Gilpin
Puget Sound Air Pollution Control Agency
110 Union Street, Suite 500
Seattle, WA. 98101-2038

Re: Compliance Status Report – September 3, 2003 Compliance Inspection

Dear Ms. Gilpin:

The above Compliance Status Report requested Method Nine readings for at least 20 minutes in any one hour from the kiln cowling and feed end of the next phase one kiln start up to determine compliance with Regulation I 9.03(a).

Attached you will find two method nine readings taken 9/11/03 and 9/30/03 taken by certified observers. Quality of the readings were affected by weather conditions, swirling winds and poor background.

Yours truly, 2

Gerald J. Brown

Manager Safety and Environmental

CC: Puljan

### VISIBLE EMISSION OBSERVATION FORM

COMPANY NAME: ASH GROLD (PMEN)	DATE:	9-1	1-03	)	STAR	T TIME: /2:46	END TIME: 12.53
ADDRESS: 3801 C. Malgine Way S.	Sec min	0	15	30	45		COMMENTS
ADDRESS: SEAT 6	1	20	25	20	20		
COUNTY: King STATE: WA ZIP: 98134	2	20	25	25	20		
PROCESS EQUIPMENT: OPERATING MODE:	3	20	20	20	20		
CONTROL FOUIPMENT: OPERATING MODE:	4	20	15	20	20		
DESCRIBE EMISSION POINT:	5	20	20	20	20		
	6	20	15	20	25		
SOURCE HEIGHT: HEIGHT RELITIVE TO OBSERVER:	7						
DISTANCE FROM OBSERVER: OBSERVER: /50 F4	8						
VEIWING ANGLE TO PLUME: 20 Deglees	9						
DESCRIBE EMISSIONS: START SEE END SEE	10						
EMISSION COLOR: IF WATER DROPLET PLUME: START: 614; END: 644; ATTACHED? DETACHED? X	11						
PLUME BACKGROUND: START END	12						
BACKGROUND COLOR: MRY SKY CONDITIONS: START GLAY-MACHEND CLAY START ONCEAST ENDOUGHS	13		L				
WIND SPEED: WIND DIRECTION: START END START END  TENDED ATTURED  OF LATING HIN (ID) TV.	14						
TEMPERATURE: RELATIVE HUMIDITY: START END START END	15				ļ		
DRAW NORTH ARROW	16						
PLUME: O	17						
SUN:	18				<u> </u>		
	19		-				
	20						
, ,	21 22						
Cervent Silo 1/2	23	-					
- K.W	24		6				
EMISSION POINT	25						
	26						
- Ple Hustell Tower	27						
1 // / <b>1</b>	28						
OBSERVERS POSITION	29						
	30						
	OBSE	RVOR	S NAM	E: M	# <	HRAD GY	
SUN LOCATION LINE	OBSE	RVOR	S SIGN	ATURE	Ma	Fishaller	DATE: 9-1603
ADDIDIONAL INFORMATION: WELLAST SKY, BJ		NIZA		ASH	GRO	ile Cerrent	
WAS A READ ABLE WITH GPTT in Back ground		IFIED		AKIMA	Regie	MAL Clear Sill;	AUHUL DATE: 9-4-03
The state of the s	CERT	TIFICA	TION N	NUMBE	R: \( \lambda	A-502-	18
							<b>▼</b>

CERTIFICATION NUMBER:

WA-FOO-41

VIEW WAS FROM TOP OF GROUPIT SILO'S



Working Together For Clean Air

www.pscleanair.org

September 24, 2003

Ph 206.343.8800

1.800.552.3565

Fax 206.343.7522

110 Union Street

Suite 500

Seattle, WA 98101-2038

Ash Grove Cement Company

c/o Craig Puljan, Plant Manager

3801 E Marginal Wy S

Seattle, WA 98134

Re:

Ash Grove Cement Company (R11339)

Disposition of the July 24, 2003 Compliance Status Report (CSR)

EXECUTIVE DIRECTOR

Dennis J. McLerran

Dear Mr. Puljan:

BOARD OF DIRECTORS

TACOMA CITY COUNCIL, CHAIR

Bill Evans

KING COUNTY

Ron Sims, Executive

SEATTLE

Gregory J. Nickels, Mayor

KITSAP COUNTY

Jan Angel, Commissioner

BREMERTON

Cary Bozeman, Mayor

PIERCE COUNTY

John Ladenburg, Executive

SNOHOMISH COUNTY

Jeff Sax, Councilman

EVERETT

Frank Anderson, Mayor

MEMBER AT LARGE

Janet Chalupnik

Based on the information provided in your Corrective Action letter dated August 19, 2003, this Agency considers the CSR --which resulted from our July 24, 2003 on-site inspection of your facility-- closed as of this date and will take no further enforcement action in this case.

Thank you for your action to ensure compliance with Agency regulations and for joining with this Agency in efforts to achieve cleaner air.

Sincerely,

Ugabeth Gilpin

Inspector

EMG/mll

Mario Miller, Supervising Inspector



## **Puget Sound Clean Air Agency**

110 Union Street, Suite 500 Seattle, WA 98101-2038 phone 206-343-8800/1-800-552-3565 fax 206-343-7522 www.pscleanair.org

# Compliance Status Report

Case No.	Registration No. 1133	39 Evaluation Da	ite: 7/24/03 Tir	Title It Manager  Zip County 98134 King  Zip Phone 98134 (206) 623-5596  ——————————————————————————————————
Name Ash Grove Cement Co	Responsible Person, Title Craig Puljan, Plant Manager Address) City Seattle, WA 98134 King Address City, State Zip Phone Seattle, WA 98134 (206) 623-5596  Served no violations of our Agency's regulations during my review of your continuous emission monitoring report dated and received by a served no violations of our Agency's regulations during my review of your continuous emission monitoring report dated and received by and received by and received by and received by a served no violations. I will share my conclusions with you either in person, over the ne, or in writing by and received by a served no violation. Please submit the following information within 10 days of your realist notice:  If you compliance inspection of your facility on July 24, 2003 you provided us with the powing main baghouse inlet temperature limits established during your 10/22-10/24/02 sour candidated 11/22/02 table 2-2 for the 10/22/02-10/24/02 test shows the following temperature is: Raw mill on: 334.0 degrees F. Raw mill off: 492.0 degrees F. Please provide an anation of the apparent discrepancies in the established main baghouse inlet temperatures.  If you compliance inspection of your facility on July 24, 2003 you provided us with the powing main baghouse inlet temperature is: Raw mill on: 334.0 degrees F. Raw mill off: 492.0 degrees F. Please provide an anation of the apparent discrepancies in the established main baghouse inlet temperatures.  If you compliance inspection of your facility on July 24, 2003 you provided us with the facility on July 24, 2003 you provided us with the facility on July 24, 2003 you provided us with the facility on July 24, 2003 you provided us with the facility on July 24, 2003 you provided us with the facility on July			
Name Ash Grove Cement Company  Location (Address) 3801 E. Marginal Way So.  Mailing Address As Above  City Seattle, WA  Mailing Address As Above  City, State Seattle, WA  Lobserved no violations of our Agency's regulations during my continuous emission monitoring report dated Agency on  Loculd not make a compliance determination because:  I need to consult with others. I will share my conclusions with y phone, or in writing by  I need more information. Please submit the following information of this notice:  1. During our compliance inspection of your facility on July 24, 2003 following main baghouse inlet temperture limits established duritest: Raw Mill On: 335.84 degrees F: Raw Mill Off: 437.9 degree report dated 11/22/02 table 2-2 for the 10/22/02-10/24/02 test show limits: Raw mill on: 334.0 degrees F. Raw mill off: 492.0 degree explanation of the apparent discrepancies in the established mai values.  2. Please provide a concise explanation explaining why the G-Cooler subject to the NSPS requirements to install a continous opacity results.	1 1			
-		Responsible Person, Title Craig Puljan, Plant Manager    City   Seattle, WA   98134   King     City, State   Zip   Phone     Seattle, WA   98134   (206) 623-5596     Agency's regulations during my review of your and received in monitoring report dated and received in the following information within 10 days of your report dated and received in the following information within 10 days of your report facility on July 24, 2003 you provided us with the magneture limits established during your 10/22-10/24/02 source F: Raw Mill Off: 437.9 degrees F. The actual source test repancies in the established main baghouse inlet temperate repancies in the established main baghouse inlet temperate in explaining why the G-Cooler baghouse exhaust is not so to install a continous opacity monitor or conduct daily monstrate compliance with the 10% clinker cooler exhaust in the stablished main baghouse in the stablished main baghouse exhaust is not so to install a continous opacity monitor or conduct daily monstrate compliance with the 10% clinker cooler exhaust as from the coal mill in the 11/22/02 source test results tables.		
Agency on	inuous emission monitor	ring report dated		-
☐ I need to consul	t with others. I will share		rith you either	in person, over the
	rmation. Please submit	the following inform	nation within	10 days of your receipt
following main be test: Raw Mill O report dated 11/2 limits: Raw mill explanation of the	eaghouse inlet temperture n: 335.84 degrees F: Rav 22/02 table 2-2 for the 10/ on: 334.0 degrees F. Ra	e limits established w Mill Off: 437.9 de 22/02-10/24/02 test w mill off: 492.0 de	during your 1 grees F. The a shows the foll egrees F. Plea	0/22-10/24/02 source actual source test lowing temperature ase provide an
subject to the NS method 9 opacity	SPS requirements to insta	Responsible Person, Title Craig Puljan, Plant Manager    City   Seattle, WA   98134   King     City, State   Zip   Phone     Seattle, WA   98134   (206) 623-5596     Of our Agency's regulations during my review of your and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring report dated and received by this or mission monitoring mission monitoring report dated and received by this or mission monitoring mission monitoring mission monitoring with the following information within 10 days of your receipt pection of your facility on July 24, 2003 you provided us with the inlet temperature limits established during your 10/22-10/24/02 source 4 degrees F. Raw Mill Off: 437.9 degrees F. The actual source test le 2-2 for the 10/22/02-10/24/02 test shows the following temperature of degrees F. Raw mill off: 492.0 degrees F. Please provide an ent discrepancies in the established main baghouse inlet temperature explanation explaining why the G-Cooler baghouse exhaust is not irrements to install a continous opacity monitor or conduct daily is to demonstrate compliance with the 10% clinker cooler exhaust		
We observed the	dioxin emissions from t			

### ASH GROVE CEMENT COMPANY



"WESTERN REGION"

August 19, 2003

Ms. Elizabeth Gilpin Puget Sound Air Pollution Control Agency 110 Union Street, Suite 500 Seattle, WA. 98101-2038

Re: Compliance Status Report – July 2003 Compliance Inspection

Dear Ms. Gilpin:

The above report request additional information:

#### 1. Main Baghouse inlet temperatures.

The discrepancy between the temperature stated and that actual established in the source test is due to an error made in converting degrees F to degrees C. The correct temperature limits are:

Raw Mill On: 334 degrees F/ 167.77 degrees C Raw Mill Off: 492 degrees F/ 255.55 degrees C

# 2. The G-Cooler is not subject to NSPS requirements to install a continuous opacity monitor or conduct daily Method 9 opacity readings.

40 CFR Part 60 defines a Clinker Cooler as "equipment into which clinker product leaving the kiln is place to be cooled by air supplied by a forced draft or a natural draft supply system." There are essentially two different types of cement clinker coolers in operation in the U.S. These being the Reciprocating Grate Cooler and the Planetary Cooler. While there are variations in the types of reciprocating grate coolers, they are all based on the same basic design. In the reciprocating grate cooler, lower clinker discharge temperatures are achieved by passing an additional quantity of air through the clinker. Because this additional air cannot be utilized in the kiln for efficient combustion, it is vented to the atmosphere, used for drying coal or raw materials, or used as a combustion air source for the precalciner.

By contrast the planetary cooler, which is the type at the Ash Grove Seattle plant, does not use any additional air for cooling. All the cooling air is drafted through the cooler tubes and is used completely in the pyro-processing through the kiln. No excess cooling air is vented from the system. 100% of the cooling air is drafted through the kiln system. A COM monitors kiln stack exhaust.

The Peters G-Cooler provides added cooling to prepare the clinker for transportation on a rubberized belt and for storage. The G-Cooler uses an indirect heat exchange system to cool the clinker, the cooling air does not contact the clinker and there is no clinker cooler exhaust gas to control. The dust collector on the secondary cooler or G-Cooler is simply for the purpose of maintaining a negative draft condition of the equipment hence minimizing any fugitive dust created through the transport of clinker through the system. It is similar in function to any of the other dust collectors such as material transfer points, finish mills, etc. Emissions generated from the affected sources associated with conveying and conveyor transfer points are regulated under 40 CFR Part 60, Subpart F and do not require opacity monitors.

3. The dioxin emissions in table 2-2 of the 11/22/02 source test is different than in the 6/10/2003 letter.

The lbs./hr shown for Coal Mill #1 in the June 10, 2003 table is incorrect. This difference is due to a typo error made in the 6/10 response to a question posed to Bob Vantuyl by Fred Austin. The attached table should be replaced in the June 10 letter and reflects the correct TEQ emission rate. The correct table was sent to Fred Austin via E-mail on June 17, 2003.

4. Planetary cooler tube water sprays were not installed as a fugitive dust control device.

The water spray system was installed in order to maintain uniform steel temperatures of the cooler tubes. Although it was not intended for fugitive dust control but it does provide added benefit in this area.

5. Thermocouple temperature range

The response range of the Main Baghouse inlet thermocouple complies with requirements specified in 40 CFR 63.1350 (f)(1)(i) for Raw Mill on and off operating conditions. The thermocouple is calibrated at temperatures ranging from 0°F to 1000°F. This is shown in the Temperature CMS Validation section of the attached Thermocouple Quarterly Performance Audit Report.

If Ash Grove can provide any further information, please contact me.

Yours truly.

Gerald J. Brown

Manager Safety and Environment

cc: Craig Puljan

### VALID RESULTS, INC.: Dioxins/Furans Toxic Equivalency Factor Calculation

#### Coal Mill #1

Client:

Ash Grove Cement

Test Dates:

10/22/02

Plant Location: Source: Seattle, WA Coal Mill 1

Source: Control Equip:

Baghouse

Test Date:				10/22	in 1 2/2002	Run 2 10/22/2002 13:42-16:52		Run 3 10/22/2002 17:53-21:04		Average	
Test Time:		٥F			·12:22 0.4		0.0		-21:04	,,	0.3
Baghouse Temperature		°F			0.4		8.5		9.9		9.7
Coal Mill Temperature					0.8 7		7.		7		7
Coal Mill Load		tons/hr tons/hr			1.6		5.8		8.7		5.4
Kiln Feed Load Clinker Load		tons/hr			5.6		9.1		0.9		3.9
Clinker Load		tons/m	Toxic	90	J.0		7.1	10	1		3.9
			Equivalency		TEO		TEO		TEO		TEO
Compound			Factor	pg/dscm	ng/dscm	pg/dscm	ng/dscm	pg/dscm	ng/dscm	pg/dscm	ng/dscm
2,3,7,8-TCDD			1	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,7,8-PeCDD			0.5	0	0.00E+00	o	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,4,7,8-HxCDD			0.1	Ö	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,6,7,8-HxCDD			0.1	0	0.00E+00	o	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,7,8,9-HxCDD			0.1	0	0.00E+00	0	0.00E+00	0	0.00E+00	ő	0.00E+00
1,2,3,4,6,7,8-HpCDD			0.1	o	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
OCDD (total)			0.001	5.50	5.50E-06	4.62	4.62E-06	4.78	4.78E-06	4.97	4.97E-06
2,3,7,8-TCDF			0.1	0.50	5.00E-05	0	0.00E+00	0	0.00E+00	0.17	1.70E-05
1,2,3,7,8-PeCDF			0.05	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
2,3,4,7,8-PeCDF			0.5	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,4,7,8-HxCDF			0.1	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,6,7,8-HxCDF			0.1	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
2,3,4,6,7,8-HxCDF			0.1	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,7,8,9-HxCDF			0.1	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,4,6,7,8-HpCDF			0.01	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
1,2,3,4,7,8,9-HpCDF			0.01	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
OCDF (total)			0.001	0	0.00E+00	0	0.00E+00	0	0.00E+00	0	0.00E+00
Sample Volume		dscm		3.3	379	3.3	355	3.2	267	3.3	334
Sample Volume		dscf		119	.349	118	.494	115	.393	117	.745
Stack Gas Flow Rate	$Q_{std}$	dscf/m		5.3	16	5.3	316	5.1	117	5,3	250
Stack Gas Velocity	V <sub>s</sub>	feet/sec		-	.59		.75	71	.51		.95
Stack Pressure	P <sub>s</sub>	inches Hg			.02		.87		.87		.92
Stack Temperature	T,	°R			2.7		1.7		7.1		3.8
•	_	%			.64		.72		2.7		.69
	%O <sub>2</sub>	% %			2.5		1.8		2.9		2.4
	ISOK			10	2.3	10	1.6	10	2.3	10	2.7
Toxic Equivalent Concentra	tion (TE	Q)									
of 17 PPDD/PCDF (ng/dscr				0.000	05550	0.0000	04620	0.0000	004780	0.000	02197
Toxic Equivalent Concentration (TEQ) of 17 PCDD/PCDF (ng/dscm TEQ@7%O2)			0.000	09340	0.000007851		0.0000	08103	0.000	03720	
Toxic Equivalent Concentra											
of 17 PCDD/PCDF per meg				0.00	5719	0.000	)4641	0.0004539		0.002184	
TEQ Emission Rate (lbs/hr)				2.481	E-14	2.051	E-15	2.066	iE-15	9.642	2E-15

Non-detected compounds were reported as zero

The Toxic Equivalency Factors utilized are from the 1989 International Standards

ng/megagram of clinker = (ng/dscm)\*(dscf/m)\*(60 min/hr)/((35.32 dscf/dscm)\*(clinker tons/hr)\*(0.9072 metric tons/short ton))

clinker tons/hour = (Kiln Feed tons/hr)\*(0.598% Efficiency)

 $lbs/hour = (ng/dscm)*(Q_{std} \ dscf/minute)*(60 \ minutes/hour)*(2.205E-12 \ lb/ng) \ / \ (35.32 \ dscf/dscm)$ 

pg/dscm = picograms per dry standard cubic meter

ng = nanograms

	Data Form 0	03-Q. T	hermoco	ouple Q	uart	erly Perfor	mance A	udit Repor	t		
Procedure 1	Procedure No.: SECMSP-003  Rev No.: 1				Ash Grove Cement Company Page:						
Rev No.: 1			Seatt	Seattle, Washington				Rev. Date: 12/12/			
Control	Loop Name/Nu	nber:	Marie (1)		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	riognici i i interio					
•	Transmitter Nu	nber:		413.BF	I.TI	l					
Calibration I							- <del></del>			***************************************	
	ription		,	ID#	c	000 200	(	Certified Ex	piration		
HART	115 275 Comm	unica t	un.	<u>14 41 53</u> 1900	5-	1458A	3/4/04				
		-latinoppi	Trans							W	
Loop Test:				As Fe	oun	d	· · · · · ·	As Left			
	4mA Test Signal:			o°							
20mA Test Signal:  Thermocouple (TC)/Digital Multin			<del></del>	100				1000			
		Multime	ter (DM)	M) Calil	brati	ion:	Calibi	ration Date:	3-,	1 . 0	
	DMM	AST	M Referen	се		* S	pecification	on (≤ ±2°F)			
mV	°F		-	J	Diffe	erence (°F)	Y	es	No		
	69.90	6	69.20		.7°		v				
<i>a</i>										n-n	
<u> 1 emperature</u>	CMS Validatio		22.62.6			~		ation Date:			
Range	Outpu		OMM Central Control Roor			m (CCR) Display Temperature (°F) ±5% F.S.					
°F	mV		°F	°F		TC - CC	CR	Expected	Yes	No	
0-250			00	.23		02	0-,235,23		v		
250-500			250	250.	1	100	O. '750'	±25°F	1		
500-750		500	- 750	500 /74	. 60	5000/1		±37°F	1/		
750-1000	Action: Any "?		000	999-10		±1°		±50°F	1		
Malfunction St Was Malfunction	dequest and description art Date & Time: on Report Form/vective action	<u>ル</u> タ Vork Req	uest deliv	Malfur	nctio Iaint	n End Date & enance Plann	er?	_Yes	No <u>N</u> 4		
Afier correctiv	ve action, attach heck attached: I Person N	DF 003-9	P DF 003	-Q or DI DF 0	F 00	3-C to verif	<i>NA</i>	rective acti		tı	
C. Comments:											
Checked By:	R. Downs	·					Date:	7-28-03			
Reviewed By: ccalq	K. Downs	A					Date: _	7/28	103		